DESCRIPTION

PARTS-SOLV H.F. is an industrial strength degreasing solvent designed to remove grease, oil, tar, carbon and other soils from parts and equipment. Special penetrating agents provide rapid and complete soil removal. PARTS-SOLV H.F. is made for use with all types of cold solution parts cleaners, manual operations and soak tanks.

DIRECTIONS

Allow **PARTS-SOLV H.F.** to circulate in parts washer until parts are clean. Stubborn deposits may require light brushing. Larger parts may be immersed in PARTS-SOLV H.F. This product is ready to use.



WECHEM, INC. 5734 Susitna Dr. Harahan, LA 70123 504.733.1152 1.800.426.0512 FAX 504.733.2218 www.wechem.com



- HIGH FLASH POINT
- FORMULATED WITH PENETRATING AGENTS

WARNING

KEEP OUT OF REACH OF CHILDREN. FOR INDUSTRIAL AND INSTITUTIONAL USE ONLY. (SEE RIGHT PANEL FOR ADDITIONAL CAUTIONS AND FIRST AID STATEMENTS.)

NET CONTENTS: U.S. GALLONS





WARNING:

Combustible liquid. May be harmful if swallowed and enters airways. Causes skin irritation. Causes eye irritation. May cause respiratory irritation. Keep away from heat/sparks/open flames/hot surfaces. No smoking. Wear protective gloves/protective clothing/eye protection/face protection. Do not breathe dust/fume/gas/mist/vapors/spray. Wash thoroughly after handling. Use in a well-ventilated area. Keep container tightly closed. Keep cool. Dispose of contents/container in accordance local/regional/national/international regulations.

IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician.

IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

IF IN EYES: Rinse continuously with water for several minutes. Remove contact lenses if present and easy to do. Continue rinsing. Call a POISON CENTER or doctor/physician.

READ SAFETY DATA SHEET BEFORE USE.

SCAN FOR SDS



