

ALUMINUM WASH PLUS is a non-caustic compound designed for use in enclosed high pressure spray cabinet systems and hot vats. This compound rapidly removes dirt, grease, oil and varnish from parts when used as directed. The high alkaline intensity and buffered wetting agents of **ALUMINUM WASH PLUS** remain strong and stable under high temperatures for long periods of time.

DIRECTIONS

HOTVAT: Add 1-2 ounces (1/16-1/8 pound); (28-56 g) of compound per gallon (3.78 L) of water in the vat. Operating temperatures must not exceed 160°F (70°C) and soak time must not exceed 30 minutes. Rinse thoroughly by soak or spray.

SPRAY CABINET (with rinse): Preheat water to 140°F (59°C). Turn on circulation pump and slowly add 1-2 ounces (1/16-1/8 pound); (28-56g) of compound per gallon (3.78 L) of water in system. Washing temperature must not exceed 160°F (70°C). Rinse temperature can be higher for faster drying. The cleaning time must not exceed 30 minutes. Operate according to equipment manufacturer's instructions. Foaming of unit may occur if correct temperature is not reached and maintained.

POWER SPRAY CABINET (no rinse): Preheat water to 140°F (59°C). Turn on circulation pump and slowly add 1-2 ounces (1/16-1/8 pound); (28-56 g) of compound per gallon (3.78 L) of water in system. Operating temperatures must not exceed 160°F (70°C) and cleaning time must not exceed 30 minutes.



Engineered Chemistries
SUPERIOR SOLUTIONS

ALUMINUM WASH PLUS

Ideal for Spray Washers and Hot Vats
Safe for Aluminum, Steel, Iron
Low Foam

DANGER

KEEP OUT OF REACH OF CHILDREN.

FOR INDUSTRIAL AND INSTITUTIONAL USE ONLY.

(SEE RIGHT PANEL FOR ADDITIONAL CAUTIONS AND FIRST AID STATEMENTS.)

NET CONTENTS: U.S. POUNDS



DANGER: May be harmful if swallowed. Causes skin irritation. Causes serious eye irritation. May cause damage to organs through prolonged or repeated exposure. Harmful to aquatic life. Causes severe skin and eye damage. Keep out of reach of children. Read label before use. Do not get in eyes, on skin, or on clothing. Avoid release to the environment.

FIRST AID

EYES: Hold the eyelids apart and flush the eye gently with large amounts of water for at least 15 minutes.

SKIN: Flush skin with cool water. Wash the exposed area with plenty of soap and water.

INHALATION: Remove individual to fresh air and get immediate medical attention. If breathing is difficult, give oxygen. If breathing stops, give artificial respiration.

INGESTION: Have person drink a glass of water immediately if able to swallow. Get medical attention immediately. Do NOT INDUCE VOMITING unless directed to do so by medical personnel. Never give anything by mouth to an unconscious person.

READ SAFETY DATA SHEET BEFORE USE.

SCAN FOR SDS



Rev. 09.2026

WEICHEM, INC.

5734 Susitna Dr. • Harahan, LA 70123

504.733.1152 • 1.800.426.0512

FAX 504.733.2218 • www.wechem.com



PW750