FOR USE ON:

Fleet Cars · Trucks and Buses Taxi Fleets · Forklifts **Construction, Agricultural and Marine Equipment** Aircraft · Golf Carts · Postal **Vehicles · Industrial Battery Backup Systems.**

DIRECTIONS:

SHAKE WELL BEFORE USING

Spray on cables, clamps, terminals, brackets, housings and entire battery surface. (Be sure cell covers are tightly sealed). Product will spray out light yellow and turn red in the presence of acid. Allow foam to work for several minutes, then flush off with water or a damp cloth. For severe corrosion, follow with a second application. If solution still turns red, acid neutralization process is not complete. Allow to set then repeat. For heavy deposits, agitation with a wire brush may be needed. If sprayed foam remains yellow... all acid has been neutralized. Allow product to dry and form residual protective film.









DANGER

Extremely Flammable Aerosol. Contains gas under pressure; may explode if heated. Causes eye irritation.

Keep away from heat, sparks, open flames, and hot surfaces. -No smoking.

Do not spray on an open flame or other ignition source. Pressurized container: Do not pierce or burn, even after use. Protect from sunlight. Do not expose to temperatures exceeding 50°C/122°F. Store in a well-ventilated place. Wash hands thoroughly after handling.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses. if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention. Dispose of contents and container in accordance with local, state and federal regulations.

CONTAINS (CAS#): Water (7732-18-5), Propane/n-Butane (68476-86-8). Sodium 4-(4-dimethylaminophenylazo)benzenesulp (547-58-0). 2-Butoxyethanol honate (111-76-2), Isopropyl Alcohol (67-63-0).

KEEP OUT OF REACH OF CHILDREN.

See Safety Data Sheet for complete safety information. 24 HOUR MEDICAL EMERGENCY: 1-800-535-5053.





WECHEM, INC.

504.733.1152 · 1.800.426.0512

FAX 504.733.2218 · www.wechem.com





NET WT: 18 OZ. (510g)